

<b>Polluted River Stretch Priority-IV</b> <b>(Bindusara River, State - Maharashtra)</b> <b><u>Latest Water Quality As per Assessment Targeted (Characteristics of River)</u></b>							
2657 - Bindusara River at Beed, near intake water pump house at Dam, Village - Paligaon, Taluka - Beed, District- Beed.							
Month	Year	pH	DO (mg/L)	BOD (mg/L)	FC MPN /100ml	TC MPN /100ml	Water Quality
January	2017	7.8	6.8	8.0	2	140	Non Complying
	2018	8.4	6.8	3.2	4	170	Non Complying
February	2017	7.9	6.9	5	2	170	Non Complying
	2018	8.1	4.6	6.2	2	110	Non Complying
March	2017	8.2	7.2	3	2	110	Complying
	2018	8	4.9	6.2	4	170	Non Complying
April	2017	7.9	7.2	3	4	170	Complying
	2018	7.66	5.4	3.2	4	130	Non Complying
May	2017	8.2	7.1	2.8	2	140	Complying
	2018	7.9	6.6	4.8	4	130	Non Complying
June	2017	8.1	6.6	4.6	2	170	Non Complying
	2018	7.3	6.8	3.2	2	110	Non Complying
July	2017	8.6	6.9	3	4	140	Complying
	2018	8.6	6.9	2.8	4	130	Complying
August	2017	8.1	6.2	3	2	130	Complying
	2018	7.7	7.1	4.8	2	110	Non Complying
September	2017	8.5	7.2	3.2	4	120	Non Complying
	2018	8.6	7.3	3.6	2	110	Non Complying
October	2017	8.8	6	3	4	120	Complying
	2018	8.34	7.18	4	2	110	Non Complying
November	2017	8.2	6.8	3	4	120	Complying
	2018	8.34	7.25	3.4	4	170	Non Complying
December	2017	8.2	6.8	3	4	120	Complying
	2018	7.9	7.19	3.4	4	170	Non Complying